


2-B

PRODUCT IDENTIFIER


SIGNAL WORD:

WARNING
ADVISO**SOLDERING
BRAZING
RODS****GHS Hazard Statement**

INGESTION: Copper poisoning can result in hemolytic anemia and kidney, liver and spleen damage.

SKIN: Prolonged contact may cause dermatitis. Contact with molten material may cause thermal burn.

RESPIRATORY: Irritating to the nose, throat, and respiratory tract. Overexposure to Copper fumes may produce metal fume fever.

**GHS Classification and Pictograms****HEALTH
HAZARDS****S.D.S Does Not Indicate a GHS PICTOGRAM for
HEALTH HAZARDS****PHYSICAL
HAZARDS****S.D.S Does Not Indicate a GHS PICTOGRAM for
PHYSICAL HAZARDS****ENVIRONMENTAL
HAZARDS****S.D.S Does Not indicate a GHS PICTOGRAM for
ENVIRONMENTAL HAZARDS****TARGET ORGAN
EFFECTS****FIRE FIGHTING
EQUIPMENT****PPE
EPP****FIRST
AID**

EYES: Check for and remove any contact lenses. Rinse immediately with plenty of water. .

SKIN: Remove contaminated clothing. Wash with soap and water. Get medical attention if symptoms occur.

INGESTION: Do NOT induce vomiting. Immediately rinse mouth and drink water a cupful of water.

INHALATION: Remove person from contaminated area to fresh air. Apply CPR if needed. Call physician if symptoms develop or persist.